

Appendix F

Site Photos

SITE PHOTOGRAPHS – GENERAL SITE CONDITIONS

Photo 1. Proposed Facility Location



Photo 2. Proposed Facility Location



Photo 3. Existing access road off Onondaga Street – looking to the East



Photo 4. Existing access road off Onondaga Street – looking to the West



SITE PHOTOGRAPHS – BIRD ASSESSMENTS

**Photo 5. Forest habitat in area of Point Count 1 –
Along NB Trail**



**Photo 6. Forest habitat in area Point Count 1 –
Along NB Trail**



**Photo 7. Forest habitat in area of Point Count 2 –
Along NB Trail**



**Photo 8. Forest/Edge habitat in area of Point
Count 6**



SITE PHOTOGRAPHS – AQUATIC ASSESSMENTS

Photo 9. Watercourse #1 (WC1) looking upstream



Photo 10. Watercourse #2 (WC2) looking downstream



Photo 11. Watercourse #2 – Indian Brook (looking upstream from the Saint John River)



Photo 12. Watercourse #2 – Indian Brook (looking downstream towards at confluence with the Saint John River)



SITE PHOTOGRAPHS – AQUATIC ASSESSMENTS (Continued)

Photo 13. Saint John River (WC3) floodplain



Photo 14. Saint John River (WC3) shoreline



Photo 15. Young (left) and mature (right) butternut (listed as Endangered under SARA) – noted along the SJ River Floodplain



Photo 16. Raccoon tracks noted along the Indian Brook shoreline.

