

Appendix F

Site Photos

SITE PHOTOGRAPHS – GENERAL SITE CONDITIONS

Photo 1. Proposed Facility Location



Photo 2. Proposed Effluent Easement to the Right of the NB Trail



Photo 3. Typical habitat in project boundary



Photo 4. Bell Aliant Easement located north of the NB Trail



SITE PHOTOGRAPHS – BIRD ASSESSMENTS

Photo 5. Forest habitat in area of Point Count 3



Photo 6. Playback recorder setup area at Point Count 3



Photo 7. Forest habitat in area of Point Count 4



Photo 8. Forest/Edge habitat in area of Point Count 5



SITE PHOTOGRAPHS – AQUATIC ASSESSMENTS

Photo 9. Watercourse #1 (WC2) where it drains to WL1



Photo 10. Watercourse #2 (WC2) looking downstream from the parking area



Photo 11. Drainage along NB trail easement towards McMonagles Brook



Photo 12. Bear Trap Brook



SITE PHOTOGRAPHS – AQUATIC ASSESSMENTS (Continued)

Photo 13. Wetland 1a (WL1a) – cattail marsh area



Photo 14. WL1a – forest wetland



Photo 15. Outlet of WL1a and Inlet of WL1b – Forest Wetland



Photo 16. Wetland 1b

